



Texture Mould Firing Schedule – 6mm System 96 Fusing Glass

Use this program as a second firing **AFTER** having full fused your glass. Once this is done you can then use a slumping schedule to make the piece into a bowl. Ensure your mould is very well primed to prevent sticking which will damage it. Use a small brush for detailed areas and dry thoroughly.

Rate (C)	Temp (C)	Hold (min)
148	738	20
148	780	10
9999 (full)	516	60
48	440	0
9999 (full)	25	0

Note:

This data is a guide only, firing programmes may need to be adjusted according to size and thickness of glass and the kiln's performance. Ensure that data is entered into the controller accurately, otherwise glass may not fuse correctly. Creative Glass Guild sells all glass, tools and materials on the basis that customers have the knowledge and ability to use them safely and in accordance with all relevant regulations and legislation.